

Tree no	Species	Age	DBH (mm)	Hgt	FSB direction
T1	<i>Tilia X europaea</i> (Common Lime)	M	1380	20(4)	n/a
T2	<i>Larix decidua</i> (European Larch)	M	500	10(8)	8(S)
T3	<i>Tilia X europaea</i> (Common Lime)	EM	420	15(5)	2.5(N)
T4	<i>Pinus sylvestris</i> (Scots Pine)	M	580	18(9)	8(E)
T5	<i>Tilia X europaea</i> (Common Lime)	EM	950	18(7)	6(E)
T6	<i>Tilia X europaea</i> (Common Lime)	EM	700	16(4)	
T7	<i>Fraxinus excelsior</i> (Ash)	M	1330	20(8)	4.5(N)
T8	<i>Acer pseudoplatanus</i> (Sycamore)	M	708	15(4)	3(N)

M = mature EM = Early Mature

North	Crown Spread			Condition	Life exp
	East	South	West		
7.5	9	10	8.5	Good	10+
5	4	4	3	Poor	10+
5	4	2.5	2	Fair	10+
6	6	3	5	Fair	10+
7	7	5	5	Fair	10+
5	5	5	4	Fair	10+
10	9	7	9	Fair	10+
8.5	7.5	2	7	Fair	10+

Remarks	Recommended work	RPR metres
Leaning South-East. Stem divides below 1.5m. Unbalanced crown shape. Crown distorted due to group pressure. Branches encroaching upon building.	Inspect stem/basal area. Remove epicormics. Prune clear of building.	15
Poor shape & form. Declining. Leaning North-East. Broken top	Retain as habitat	6
Epicormics on stem. Suckers around stem base. Crown distorted due to group pressure. Branches encroaching upon building.	Remove major deadwood. Remove broken/damaged branches. Prune clear of building.	5.04 6.96
		11.4
		8.4
Stem divides above 1.5m. Some die back within upper crown and likely due to As dieback (<i>Hymenoscyphus fraxineus</i>)	Prune clear of building. Recommend 10 -15 % Crown reduction to reduce loading.	15
Leaning North. Stem divides below 1.5m.		8.5

RPA m2

706.95

113.11

79.81

152.2

408.33

221.7

706.95

227.01