THE STAR INN, HARBOTTLE

CONTAMINATION ASSESSMENT







P1 – View of hard paved courtyard / garages from upper rear garden



P2 – View of hard paved courtyard from road entrance



P3 – Asbestos cement roof sheets to north roof slope



P4 – View of interior of former stables




P5 – Rear agricultural field to north of site



P6 – Residential use to east of site

SKETCH PLAN



PUBLIC ROAD