

Associated Photos

View from the campsite small visitor parking area to site of land for development. Note the spoil heap is still in place in this photo.



View from campsite small visitor parking area to site of land for development. Note the spoil heap has been removed and there remains a much lower slope up to the main level of the land.



View from existing drainage ditch back to Tweed House, Wansbeck House on the right. It is 30 m across, corner to corner.



View along S boundary towards campsite, drainage ditch starts at junction of fences.



Drainage ditch. Although still functioning it will be cleared by hand digging.



Example of debris removed, some of the foundation blocks that were dumped in a pile.

