



Haystore from south elevation



Haystore north rear elevation



Byre from the door, concrete cattle stall removal on going





North elevation of Byre and Barn



Barn South elevation rubble soil at door

is old cobbled floor and stone / concrete feed trough removal



Inside of barn floor and stone /concrete

feed trough removal on going.



Haystore and Byre south elevation

rubble and old floor removal on going

