

Dunshiel Farm, Elsdon – NE19 1AQ

Non Mains Drainage Statement

The property at the above is currently served by a Septic Tank

There will be no further increase in sleeping accommodation and the existing system will be used.

The outfall is to the existing adjacent burn and is the reason no percolation test holes have been carried out.

The nearest main sewer is located in the village of Elsdon and is approximately 1 mile away. It is not feasible to connect to this system due to the distance and the crossing of Third Party land

Michael Rathbone ACABE

Architectural & Surveying

5 Church Hill

Chatton

NE66 5PY

Tel: [REDACTED]

Mob: [REDACTED]

Email: [REDACTED]